

From: [Chuck Pinney](#)
To: [Charlton Johnson](#); [Christina Adkins](#)
Subject: Re: ECO 1156
Date: Friday, May 10, 2024 1:10:56 PM
Attachments: [image001.png](#)
[Outlook-Descriptio.png](#)

Christina and Charlie,

The proposed modification to the ES&S EVS 6200 and EVS 6300 systems contained in ECO-1156 adds an extension to the sensor arm that is used with the DS950 central scanner. The modification is designed to address situations where there is a small chance of a possible error in the operation of that tray.

I agree with Tom that the proposed modification is de minimis and does not adversely impact the security or performance of the system. Because this modification is designed to prevent a possible error in the operation of that device, I recommend approval of this modification.

Thanks,

Chuck Pinney

Senior Staff Attorney – Elections Division
Office of the Texas Secretary of State
1019 Brazos Street | Rudder Building, 2nd Floor | Austin, Texas 78701
1.800.252.VOTE (8683)
elections@sos.texas.gov | www.sos.texas.gov

For Voter Related Information, please visit:



The information contained in this email is intended to provide advice and assistance in election matters per §31.004 of the Texas Election Code. It is not intended to serve as a legal opinion for any matter. Please review the law yourself, and consult with an attorney when your legal rights are involved.

From: Tom Watson <txtwatson@gmail.com>
Sent: Friday, May 10, 2024 12:11 PM
To: Charlton Johnson <CJohnson@sos.texas.gov>
Cc: Chuck Pinney <CPinney@sos.texas.gov>
Subject: Re: ECO 1156

CAUTION: This email originated from OUTSIDE of the SOS organization. Do not click on links or open attachments unless you are expecting the email and know that the content is safe. If you believe this to be a malicious or phishing email, please send this email as an attachment to Informationsecurity@sos.texas.gov.

Charlton,

I have reviewed the material and I agree with the VSTL that ECO-1156 is de minimis. The ECO will not cause any change in the security, reliability, or operation of the election systems utilizing this ballot box. The ECO has been incorporated into the EVS 6400 system which was tested by a VTSL. This is important because if the change caused a reliability or operation issue, it would have been detected due to the large number of ballots processed by the DS950 during the testing campaign.

Tom Watson
Examiner